

MARTINDALE ELECTRIC CO.

PO Box 430 Cleveland, OH 44107 • Phone (216) 521-8567 • Fax Local 521-9476 / USA & Canada (800) 344-9191 • E-Mail: sales@martindaleco.com

Digital Multimeter

with Adjustable Display

Dimensions:

7-1/2" x 3-1/2" x 1-1/2"

Features:

- ⇨ Measurement functions include AC/DC Voltage and Current, Resistance, Diode, Continuity and Transistor (9 Functions over 30 Ranges)
- ⇨ Auto Power Off
- ⇨ Overrange, Polarity, and Low Battery Indications
- ⇨ Color Coded Input Jacks with Overload and Current Fuse Protection
- ⇨ Complete with Test Leads, 9V Battery, and Holster

Ranges:

DC Voltage: 200mV, 2V, 20V, 200V, 1000V

AC Voltage: 200mV, 2V, 20V, 200V, 750V

DCCurrent: 20µA, 200µA, 2mA, 20mA, 200mA, 2A, 10A

AC Current: 20µA, 200µA, 2mA, 20mA, 200mA, 2A, 10A

Resistance (Ω): 200, 2K, 20K, 200K, 2M, 20M, 200M

Catalog Number

Digital MultimeterVAOTMV110

Net Weight 1 lb. 4 ozs., Shipping Weight 3 lbs.



Mirrored Scale

UL Listed

Dimensions:
5-1/4" x 7" x 3-1/8"

Catalog Number

Model 260-8 complete with leadsVAOT2608

Model 260-8P complete with leadsVAOT2608P

Net Weight 3-1/2 lbs., Shipping Weight 5 lbs.

Carrying Case for either of aboveVAOT260C

V.A.O. Testers

Simpson Models 260-8 and 260-8P

Features:

- ⇨ **Model 260-8** — world famous; offers movement overload protection, input protection, increased stability, and self-shielded meter movement.
- ⇨ **Model 260-8P** — is identical to Model 260-8, but with built-in meter and tester protection approaching 100% which makes this instrument virtually GOOF-PROOF. A reset button pops out indicating overload. Circuits cannot be reset while the overload is present. This is especially important for inexperienced operators.

Ranges:

Volts, D.C.: 0-0.250, 1, 2.5, 10, 50, 250, 500, 1000.

Volts, A.C.: 0-2.5, 10, 25, 50, 250, 500, 1000.

Amperes, D.C.: 0-10 (250 MV Drop).

Amperes, A.C.: up to 250 amperes in 6 ranges with Model 150-2 Amp-Clamp.

Milliamperes, D.C. only: 0-1, 10, 100, 500.

Ohms: Rx1 0-2000 (12 center)

Rx100 0-200,000 (1,200 center)

Rx10,000 0-20 megohms (120,000 center)

dB Scale, (IMW 600 ohms) - 20 to + 10, - 8 to + 22,
+ 6 to + 36, + 20 to + 50.

A.C./D.C. Digital Clamp-On Multimeter

Full Function Digital Multimeter

Features:

- ⇨ Measures AC/DC Current plus Voltage, Resistance and Diode
- ⇨ 1.3" clamp jaw opening
- ⇨ Large 3-1/2" digit LCD with low battery indication
- ⇨ Temperature measurements on 38095F
- ⇨ True RMS AC response on 38095F
- ⇨ Peak hold to store and recall motor in-rush current; Data Hold; overload protection
- ⇨ Dual hall effect sensors provide 2% DCA accuracy
- ⇨ Manual DCAzero adjust improves accuracy
- ⇨ Complete with 9V battery, carrying case, test leads and bead wire K thermocouple probe for 38095F



Ranges:

DC Voltage: 200mV*, 200V, 600V

AC Voltage: 200V, 600V

(*Range applies to Model 380922 only.)

AC/DCCurrent: 200A, 1000A or 2000A
(AC Frequency Response 40 to 400 Hz)

Resistance (Ω): 2000

Temperature: -40 to 2000°F

Dimensions:

9" x 3" x 1-1/2"

Catalog Number

Model 380922 1000A AC/DC Clamp-On + DMM,
(without temperature function)VAOT380922

Model 380923 2000A AC/DC Clamp-On + DMM,
(without temperature function)VAOT380923

Model 38095F 1000A True RMS AC/DC Clamp-On +
DMM + Temperature FunctionVAOT38095F

Net Weight 1 lb. 10 ozs., Shipping Weight 3 lbs.