


Rubrite flexible abrasive cleaning stones are excellent for removing surface imperfections from any metal. Mildly abrasive, they do only enough cutting to produce a high polish and fine finish. They are slow-wearing, non-loading, and will not gum or dust.

Recommended in commutator maintenance for periodic cleanup of surface, or for polishing the commutator after grinding with Diamond D commstones. They can also be recommended to provide a smooth, clean finish on machined parts, etc.

Size and Grade Selection

We make Rubrite in only one grade. When using on commutators and slip rings, we suggest you use as large a Rubrite as will easily fit between your brush riggings.

If you don't see the exact size you want, remember you can always special order size up to a maximum of 12" x 5" x 2". Please specify size and quantity for us to quote price and delivery.



• Fractional Motor Handle

This type is used to clean and polish fractional horsepower motor commutators. **Specify catalog number when ordering.**

Description			Catalog Number
L.	W.	T.	
3/4"	3/8"	1"	RUBBX6249



• Railway Handle

This handle is mounted vertically, which gives excellent leverage. **Specify catalog number when ordering.**

Description			Catalog Number
L.	W.	T.	
2"	1-1/2"	2"	RUBBX6225
2"	2"	2"	RUBBX6226
3"	2"	2"	RUBBX6227
3"	3"	2"	RUBBX6228
4"	3"	2"	RUBBX6229



• Saw Handle

This type is used to clean and polish fractional horsepower motor commutators. **Specify catalog number when ordering.**

Description			Catalog Number
L.	W.	T.	
5"	1"	2"	RUBBX6290



MARTINDALE • PO Box 430 • Cleveland, OH 44107

Phone (216) 521-8567 • Fax Local 521-9476 / USA & Canada (800) 344-9191

E-Mail: sales@martindaleco.com

Web Site: www.martindaleco.com



• Tramway Handle

This handle is mounted at a 45° angle, which gives good access to awkwardly positioned commutators. Specify catalog number when ordering.

Description			Catalog Number
L.	W.	T.	
2"	1-1/2"	2"	RUBBX6235
2"	2"	2"	RUBBX6236
3"	2"	2"	RUBBX6237
3"	3"	2"	RUBBX6238
4"	3"	2"	RUBBX6239



• Pocket Handle

This Rubrite is excellent for burnishing small motor and generator commutators. Specify catalog number when ordering.

Description				Catalog Number
L.	W.	T.		
1-3/4"	3/4"	1"		RUBBX6245
2"	3/4"	1"		RUBBX6246
1-3/4"	1"	1"		RUBBX6247
2"	1"	1"		RUBBX6248

• Unmounted



This type can be used for hundreds of jobs — including metal cleaning, commutator burnishing and rust removal. Specify catalog number when ordering.

Description	Catalog Number
3/8" x 3/8" x 5"	RUBBX6250
3/8" x 1/2" x 5"	RUBBX6251
3/8" x 5/8" x 5"	RUBBX6252
3/8" x 3/4" x 5"	RUBBX6253
1/2" x 1/2" x 5"	RUBBX6254
1/2" x 3/4" x 5"	RUBBX6255
1/2" x 1" x 5"	RUBBX6256
5/8" x 1" x 5"	RUBBX6259
3/4" x 3/4" x 5"	RUBBX6260
3/4" x 1" x 5"	RUBBX6261
1" x 1" x 5"	RUBBX6262
1" x 1-1/2" x 5"	RUBBX6263
1" x 2" x 5"	RUBBX6264
1" x 3" x 5"	RUBBX6266
1" x 4" x 5"	RUBBX6268
1" x 5" x 6"	RUBBX6269
2" x 5" x 6"	RUBBX6270
1/8" x 1" x 5"	RUBBX6271

